

Municipality of Zagubica,

Trg Oslobodjenja 1, 12320 Zagubica, Republic of Serbia

CLARIFICATIONS 1

Programme	Interreg IPA CBC Romania – Serbia Programme	
Due to ad didla	Rehabilitation and Modernization of the Public Lighting System	
Project title	Lenauheim -Zagubica	
lame of the Contracting Municipality of Zagubica, Trg Oslobodjenja 1 , 12320 Zagubica,		
uthority Republic of Serbia		
Tender procedure	Public lighting modernization works	
Reference No	RORS 425 - 8/2022	
Datum, Mesto / Date, Place	06.04.2023, Zagubica/Serbia	

No	Question	Answer
1	DESCRIPTION OF THE TECHNICAL CHARACTERISTICS OF THE REQUESTED TYPES OF LAMPS	ISO9001, ISO50001 or equivalent are required for this
	You are stating: The lamp manufacturer must have the following ISO	tender. Reason for this is that they are relevant standards
	certificates: ISO9001, ISO50001	concerning quality of product
	I am of the opinion that stated is not, by no means, technical characteristic of the lamp, nor I see any relation between this	manufacture process (ISO 9001) and specifies
	condition and quality of lamps.	requirements for management
	Furthermore, by insisting on implementation of ISO 50001 standard	practices that are important to
	by the manufacturer, absurd situation might happen, in which you would have to discard the offer of higher quality, more efficient and	obtain improved energy performance (ISO50001).
	even cheaper, due to the fact that not all renowned manufacturers are	
	implementing mentioned standard. Moreover, by doing so, you would be acting in contrast to ISO 50001	
	standard and you would cause impermeable damage to the Purchaser,	
	i.e. your Municipality, because throughout the exploitation, which is next 25 years, you would be spending energy that is not cheap, and	
	would be getting more expensive every day.	
	By showing unnecessary care for energy management of lamp	
	manufacturers, in long term you are renouncing your own energy management goals and you're causing detriment to the Municipal	
	budget.	
	I assume that such absurd request was result of negligence of someone who was helping with the preparation of technical documentation (or	
	maybe not), thus, I'm kindly asking you to make necessary	
	amendments and remove this request from the description of lamps.	

Safet Pavlovic Mayor of Zagubica Municipality